


REMARKS

If any questions arise during the processing of this amendment, the undersigned attorney would welcome and encourage a telephone conference at 512.428.9872.

Respectfully submitted,



Joseph P. Lally
Reg. No. 38,947
ATTORNEY FOR APPLICANT(S)

P.O. Box 684749
Austin, Texas 78768-4749
512.428.9870
512.428.9871 (FAX)

JPL/mm

Attachments

TEST RESULTS		INTERNAL LINK STATS		ADVISOR ENGINE OUTPUTS		
Test Pattern	BER statistic	HF Jitter (%UI)	Frequency Offset (ppm)	Issue	Cause(s)	Next Step
PRBS (7 BIT)	10 ⁻¹²	< 50	< 200	None	N/A	PRBS (31 BIT)
PRBS (31 BIT)	10 ⁻¹²	< 50	< 200	None	N/A	None
PRBS (31 BIT)	10 ⁻¹⁰	> 75	< 200	Channel	HF jitter	None
PRBS (31 BIT)	10 ⁻¹⁰	< 50	> 500	Application	Freq. Offset	None
PRBS (31 BIT)	10 ⁻¹⁰	< 50	< 200	Link	Jitter Tolerance	JTPAT
JTPAT	10 ⁻⁸	< 50	< 200	Channel	Group Delay	None
JTPAT	10⁻¹² 10 ⁻¹⁰	< 50	< 200	Link	Jitter Tolerance	None

190
192
194
196
198
202
204
206

FIG 4

